Snow Pit Profile
Flanders Cirque
Northern Gallatin, MT
Elevation (ft) **9350**
Aspect: **97**
Specifics:

Observer: **Mike Best**
Thu Jan 12 12:30:00 MST 2012
Co-ord: **N W**
Slope: **30**
Wind loading: **no**

Stability on similar slopes: **Good**
Air Temperature: **-8 C**
Sky Cover: **Clear**
Precipitation: **None**
Wind: **NE Light Breeze**

PF40 HS138
Stability Test Notes:
116: On Crust
116: on Crust

Layer note
115-116: F
74-75: dec
49-50: dec



Notes: HST from 1/10 not bonding well to MFcr. Crust is able to cap FCsf from last week under this light load. Midpack still has layering but is unreactive tests. Decomposed Cr at 92 looked suspect in pit wall but unreactive to tests.

Advisory Region
Northern Gallatin
Northern Gallatin, 2012-01-13